Approved For Release	2002/06/18 : CIA-RDF	74B00836R000300020 カジンス ましょ	027-7	i i i i i i i i i i i i i i i i i i i
	. : D A ILLEGIB	The second secon	DIA	A
			and the second). See a
			тион	E
	FEB 66			II 13 89337 25X1A
		4	11/1-40	25/14
	\$15 (S)		જારા જે વ્યક્ત હો	1A
	NT-LOGS			

AND AFCS: WEEKLY REPORT 14 FEB THRU 20 FEB 66.

- B. FLT NR 2, MACH VARIATIONS AT TIMES DURING FLT. NO CORRECTVE ACTION. TURN AROUND FLT.
- S. FLT NR 3, BASIC A/P VERY GOOD, MACH HOLD TWO TO THREE KNOTS
 MARIATIONS. CORRECTIVE ACTION: REPLACED FLIGHT CONTROLLER FOR VERY
 MARIATIONS PITCH INTEGRATOR.
- ALOT REPORTED NO HEADING HOLD OR BDHI OR TURN KNOB RESPONSE.

 **CORRECTIVE ACTION: BAD ROLL SERVO ACTUATOR. DURING PRE-FLT


 **SOM ERRECTING VG WAS DISCOVERED IN 2171 PLATFORM. AHRS

 **TOTATER INDICATION SHOWED 3.5 DEG ERROR FROM ERRECTED POS.

nne of extent which have no been a fire a **fromeited.**

Approved For Release 2002/06/18 : CIA-RDP74B00836R000300020027-7

BEFLACED PLATFORM. S/N 447. TOTAL TIME 130 HRS.



Approved For Release 2002/06/18: CIA-RDP74B00836R000300020027-7

HAR PAT BILD, MACH HOLD ENGAGED TWO KNOTS BELOW SCHEDULE. No service of mach straigh for Leaks and Mull, Normal. Reset integrator and straight for leaks and mull, normal.

TO WEST MY A. VER GOOD

ANTICLE 384: DURING ROLL OUT OF PREHEADING SELECT TURNS

AND 5 DEG LEFT OF HEADING. CORRECTIVE ACTION: ADJUSTED?

FROM 19TEGRATOR AND ADJUSTED PREHEADING SELECT BACK

HEGLES.

RND OF MESSAGE